



Brandschutznormen/*Low Flammability tests*

| Artikel | Deutschland DIN 4102 Part 1 (B2) DIN 53438 | Frankreich NF-P 503 NF M1 | Frankreich NF-P 503 NF M2 | Österreich ÖNORM B3825 | Europa EN 1021-1+2 | Schiffe IMO FTPC P8 | Großbritannien BS 5852-IS 0+1 | MVSS 302 ISO 3795 DIN 75200 | Italien Classe Uno (IM) |
|----------------|---|---------------------------------|---------------------------------|------------------------------|-----------------------|------------------------|-------------------------------------|-----------------------------------|-------------------------------|
| Arilano | | | | | | | | | |
| Basis | | | | | | | X | | |
| Bresta | | | | | | | | | |
| Canasta | | | | | | | | | |
| Candela | | | | | | | | | |
| Flor 66 | | | | | | | | | |
| Lord | X | | | | X | | X | | X |
| Mano-S | | | | | | | | | |
| Neptun | | | | | X | X | X | | |
| Palatexo | X | | X | X | X | | X | X | X |
| Palena | X | | X | X | X | | X | X | X |
| Palma | X | | X | X | X | | X | X | X |
| Paradino | X | | X | X | X | | X | X | X |
| Paradino Cosmo | X | X | | X | X | | X | X | X |
| Parona NF | X | X | | X | X | | X | X | X |
| Plata | X | | X | X | X | | X | X | X |
| Prince | | | | | | | | | |
| Princess | X | | | | X | | X | | X |
| Queen | | | | | | | | X | |
| Sarano | | | | | X | | | | |
| Socodilo Flash | | | | | | | | | |
| Soliena FLS | X | | X | X | X | | X | X | |
| Somosa FLS | X | | X | X | X | | X | X | |
| Sontario FLS | X | | X | X | X | | X | X | |
| Sopytana FLS | X | | X | X | X | | X | X | |
| Sorentiko | | | | | | | | | |
| Sotega | | | | | | | | | |
| Sotega FLS | X | | X | X | X | | X | X | |
| Tundra | | | | | | | | | |
| Tundra/Techno | | | | | | | | | |

Verarbeitung: Problemlose Verarbeitung nach allen in der Polsterindustrie üblichen Verfahren (Nähen, Heften, Kleben, Nageln, HF-Schweißen). Keine lösungsmittelhaltigen Kleber einsetzen.

Reinigung: Bei normaler Verschmutzung einfach mit einem feuchten Tuch abwischen. Besonders empfehlenswert ist die Verwendung eines handelsüblichen Mikrofasertuches. Starke Verschmutzung mit der Lauge eines handelsüblichen Feinwaschmittels entfernen.

Processing: Troublefree handling in usual upholstery-industry processes (sewing, tacking, gluing, nailing, HF-welding). No solvent adhesives to be used.

Cleaning: Soiled areas can be cleaned with a damp cloth. Particulary recommended is the use of a commercially available microfibre cloth. Stubborn stains require treatment with a commercial mild action detergent.